



भारत सरकार / GOVERNMENT OF INDIA



केन्द्रीय लोक निर्माण विभाग / CENTRAL PUBLIC WORKS DEPARTMENT



कार्यपालक अभियंता का कार्यालय / O/o THE EXECUTIVE ENGINEER

तीसरा तल, केन्द्रीय निर्माण सदन, सेक्टर-10-A, च-3 सर्कल के पास, गांधीनगर - 382010

3<sup>rd</sup> floor, Kendriya Nirman Sadan, Sector-10-A, Near CH-3 Circle,

Gandhinagar-382010. ☎ 079 - 29660757 ☎ 079 - 29644033

☎: eeacd.cpwd@gov.in , eeacdcpwd@gmail.com, Website : https://cpwd.gov.in



सं. 23(30)/का.अ./अहमदाबाद/हिन्दी/2021/ 695

दिनांक : 19/05/2021

सेवामें,

प्राचार्य,

केन्द्रीय विद्यालय नं.1, एम.आर. केम्पस,

शाहीबाग, पुलिस आयुक्त कार्यालय के पास,

शाहिबाग, अहमदाबाद - 380 004.

Email ID : kvno1shahibaugfs@yahoo.co.in

विषय : Obtaining safety certificate of School Main building and Primary Red Building, KV Shahibaugh.

संदर्भ : आपके कार्यालय का पत्र संख्या 12099/Buil Cor/2021-22/KV SBAG ABD/ADMN/60

दिनांक 01/05/2021

This is in reference to above subject, it is submitted that Kendriya Vidhyalay-01, Shahibaugh School Main building and Primary Red Building is found structurally safe on visual inspection as no significant structural reports were noticed in beams & columns.

However following points need urgent attention as it may risk the structural safety of building.

**Main School Building :-**

- 1) Dampness on the walls at many places.
- 2) Leakages observed in toilet, Bathroom area resulting in falling of plaster / concrete patches.
- 3) Cracks are seen on R.C.C. vertical chhajja fins and RCC columns at many places, which result in falling of concrete lumps if left unattended.
- 4) RCC terrace water tanks are damaged. Concrete covers are falling down.

Preliminary estimate for these work has already been submitted.

**Primary Red Building :-**

Mangalore tiles & wooden battens in roofing at many places are broken / disturbed resulting in seepage at many places. Some cracks / Peeling of pointing work are observed at various places in brick work which require immediate attention.

Preliminary estimate for these work has already been submitted.

(अजित निकम)

कार्यपालक अभियंता

के.लो.नि.वि., अहमदाबाद

प्रतिलिपि :

- 1) सहायक अभियंता-II, के.लो.नि.वि., अहमदाबाद ।

कार्यपालक अभियंता



भारत सरकार / GOVERNMENT OF INDIA

केन्द्रीय लोक निर्माण विभाग / CENTRAL PUBLIC WORKS DEPARTMENT



कार्यपालक अभियंता (अहमदाबाद) का कार्यालय / O/o THE EXECUTIVE ENGINEER (AHMEDABAD)

तीसरा तल, केन्द्रीय निर्माण सदन, सेक्टर-10-A, च-3 सर्कल के पास, गांधीनगर - 382010

3<sup>rd</sup> floor, Kendriya Nirman Sadan, Sector-10-A, Near CH-3 Circle, Gandhinagar-382010.

☎ 079 - 29660757 ☎ 079 - 29644033 ✉ eeacd.cpwd@gov.in, eeacdcpwd@gmail.com,

सं. 54(259)/का.अ./अहमदाबाद/हिन्दी/2022/ 1366

दिनांक : 19/09/2022

सेवामें,

प्राचार्य,

केन्द्रीय विद्यालय नं.1, एम.आर. केम्पस,

शाहीबाग, पुलिस आयुक्त कार्यालय के पास,

शाहीबाग, अहमदाबाद - 380 004.

Email ID : kvno1shahibaugfs@yahoo.co.in

विषय : Safety Certificate of Main building & Primary building.

संदर्भ : आपके कार्यालय का पत्र दिनांक 25/8/2022.

महोदय,

The following is intimated in this regard.

**1) Main Building :**


It is learnt that the age of main building is approximate 35 years. A renovation work has been done recently in the building & during the work it was observed that some structural members have developed cracks, columns of the shafts had vertical cracks. During the dismantling of roof waterproofing, it was observed that the slab concrete cover was peeling off. Such cracks wherever found were suitably repaired.

At present, as per the visual inspection, structure doesnot show distress or sagging. However keeping in view of the age of the building, it is recommended that structural audit from a Government engineering college or Institute of repute may be carried out by you, to assess the structural safety of the building.

**2) Primary Building :**

It is a very old heritage building with masonry load bearing structure with steel structural members retrofitted. As per the visual inspection the building doesn't show distress or sagging.

However keeping inmind the age of the building, structural audit for this building is also recommended.

  
(सारांश कटारिया)

कार्यपालक अभियंता (अहमदाबाद),

के.लो.नि.वि., गांधीनगर

प्रतिलिपि :

1) उपायुक्त, केन्द्रीय विधालय संगठन, क्षेत्रीय कार्यालय अहमदाबाद, सेक्टर-30, गांधीनगर ।

Email ID : kvsroadmn@gmail.com

2) सहायक अभियंता-II, के.लो.नि.वि, अहमदाबाद ।

कार्यपालक अभियंता (अहमदाबाद)

केन्द्रीय विद्यालय नं-1, शाहीबाग,  
अहमदाबाद गुजरात, कोड - 380004  
दूरभाष - 079-25626493  
फैक्स - 079-25628282  
सीबीएसई संबंधन संख्या - 400001  
सीबीएसई विद्यालय क्रमांक - 14088  
के वि सं स्टेशन क्रमांक - 001  
के वि सं विद्यालय क्रमांक - 1003



KENDRIYA VIDYALAYA NO.1, SHAHIBAUG,  
AHMEDABAD  
(GUJARAT) PIN CODE 380004  
Email: kvno1shahibaugs@yahoo.co.in  
website: https://mreahmedabad.kvs.ac.in  
CBSE AFFILIATION NO.: 400001  
CBSE SCHOOL CODE: 14088  
KVS STATION CODE - 001  
KV SCHOOL CODE: 1003

Ref.No.12029/Bui Corre/2022-23/KV AHMD SBAG/ADMN/543

Date: 27.02.2023

To  
The Deputy Commissioner  
Kendriya Vidyalaya Sangathan(AR)  
Gandhinagar - 382030.

Mail/Speed Post

Sub: Approval for structural stability assessment of School Building  
at KV No.1 Shahibaug Ahmedabad.


Respected Madam,

It is to bring to your notice that the quotation for structural stability assessment of School Building and Principal Residence at KV No.1 Shahibaug, Ahmedabad received from Vishwakarma Government Engineering College, Chandkheda Ahmedabad is being forwarded to you. Kindly approve the quotation and release the fund for the same to that urgent action may be taken for safety of Structural stability of Vidyalaya building including Government accommodation.

Kindly approve the expenditure of Rs. 7000/- for charges of visiting of Structural audit of the School Building.

Thanking you,

Yours faithfully,

  
(VIVEK YADAV)

PRINCIPAL  
Principal  
केन्द्रीय विद्यालय  
Kendriya Vidyalaya  
शाहीबाग, अहमदाबाद  
Shahibaug Ahmedabad-4

Encl: (1) Copy of Quotation for Structural stability assessment from Vishwakarma Clg,  
Visat-Gandhinagar road, Chandkheda, Ahmedabad.





भारत सरकार / GOVERNMENT OF INDIA

केन्द्रीय लोक निर्माण विभाग / CENTRAL PUBLIC WORKS DEPARTMENT



कार्यपालक अभियंता (अहमदाबाद) का कार्यालय / O/o THE EXECUTIVE ENGINEER (AHMEDABAD)

तीसरा तल, केन्द्रीय निर्माण सदन, सेक्टर-10-A, च-3 सर्कल के पास, गांधीनगर - 382010

3<sup>rd</sup> floor, Kendriya Nirman Sadan, Sector-10-A, Near CH-3 Circle, Gandhinagar-382010.

☎ 079 - 29660757 ☎ 079 - 29644033 ✉ eeacd.cpwd@gov.in, eeacdcpwd@gmail.com,

सं. 54(259)/का.अ./अहमदाबाद/हिन्दी/2023/872

दिनांक : 19/07/2023

सेवामें,

पाचार्य,

केन्द्रीय विद्यालय नं.1, एम.आर. केम्पस,

शाहीबाग, पुलिस आयुक्त कार्यालय के पास,

शाहिबाग, अहमदाबाद - 380 004.

Email ID : kvno1shahibaugfs@yahoo.co.in

विषय : Safety Certificate of Main building & Primary building.

संदर्भ : आपके कार्यालय का पत्र संख्या 12029/Buil Cor/2022-23/KV SBAG ABD/AMN/192

दिनांक 07/07/2023.

महोदय,

Vide your above referred letter safety certificate was sought from this office, in this connection, this is to intimate that CPWD is not carrying out day to day maintenance & repair of the school infrastructure & hence CPWD can not issue such certificate. However following is intimated for your necessary action.

#### 1) Main Building :


It is learnt that the age of main building is approximate 36 years. A renovation work has been done in 2021-22 in the building & during the work it was observed that some structural members have developed cracks, columns of the shafts had vertical cracks. During the dismantling of roof waterproofing, it was observed that the slab concrete cover was peeling off. Such cracks wherever found were suitably repaired.

Keeping in view of the age of the building, it is recommended that structural audit from a Government engineering college or Institute of repute may be carried out by you, to assess the structural safety of the building.

#### 2) Primary Building :

It is a very old heritage building with masonry load bearing structure with steel structural members retrofitted. As per the visual inspection the building doesn't show distress or sagging.

However keeping in mind the age of the building, structural audit for this building is also recommended.

  
(सारांश कटारिया) 19/7


कार्यपालक अभियंता (अहमदाबाद),

के.लो.नि.वि., गांधीनगर

प्रतिलिपि :

1) उपायुक्त, केन्द्रीय विद्यालय संगठन, क्षेत्रीय कार्यालय अहमदाबाद, सेक्टर-30, गांधीनगर ।  
Email ID : kvsroadmn@gmail.com

2) सहायक अभियंता-II, के.लो.नि.वि, अहमदाबाद ।

  
कार्यपालक अभियंता (अहमदाबाद)